Thursday, 7/12/2007 10:39:29 AM

Kim ปซากรton

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number Estimate Number : 33523

: 12681

P.O. Number This Issue

: NIA

: 7/12/2007,

: NC

: NAA First Issue : 31509

Previous Run Written By

Prsht Rev.

Checked & Approved By

Comment

New Issue 07-01-22 EC

S.O. No. :

: SMALL /MED FAB

Project Number **Drawing Revision**

Material

Drawing Name

Part Number

Drawing Number

Due Date

: D3594043

D3594 REV A

: DOOR DOUBLER

: 7/17/2007

: N/A

: A

Qty:

4 Um:

Each

Additional Product

Job Number:



Seq. #:

Description:

1.0

M6061T6S080

Comment: Qtv.: 6061-T6 .080 Sheet

Batch:

2.1420 sf(s) .0.5355 sf(s)/Unit Total: M 10\$984

6061-T6 .080 Sheet

2.0

WATER JET



Comment: FLOW WATER JET

1-Cut as per Dwg D3594 Dwg Rev: ____

Prog Rev:__

B 07-07-13

2-Deburr if necessary

3.0 QC2

SECOND CHECK

B 67-07-13

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

Comment: SECOND CHECK

5.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1

Comment: SMALL & MEDIUM FAB RESOURCE 1 C'SINK AS PER DWG D3594

CBD



Dart /	Aeros _!	pace	Ltd
--------	--------------------	------	-----

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
		*								

Part No: D3594-043 PAR #: NA Fault Category: PRO - Sm/ned Fro NCR: Yes No DQA: Date: 07.07.18

QA: N/C Closed: Date: 07.07.23

NCR:3	3527	W	ORK OR	DER NON-CONFORMANCI	E (NCR)		/	·	
DATE	CTED	Description of NC Section A Corrective Action Section B Initial Action Description Sign &				Verification	Approval	Annrous	
DATE	STEP	Section A	Initial Chief Eng	,		Section C	Approval Chief Eng	Approval QC Inspector	
07/07/13	也	holes (Allholes) are embloyedy (egg shopes)		Scrop and Destroy and Replace		80		Sn	
	20	R.C. Mixing Lbe was finished	Pasiour	CHANGED MIXING TUBE	13 0707,-13	07/07/13	Posjogy	Aspis	
Muzib	5-0	I pant the hole is two deep on the c'sink! LC: Human error	/ .	1 10 5 10	mF-7-07-11	07/07/06	dasion	Poror	
		Q:>1042			, w		NOX 042		

NOTE: Date & initial all entries

Thursday, 7/12/2007 10:39:30 AM Date: User: Kim Johnston **Process Sheet** Drawing Name: DOOR DOUBLER Customer: CU-DAR001 Dart Helicopters Services Part Number: D3594043 Job Number: 33523 Job Number: Description: Seq. #: Machine Or Operation: INSPECT WORK TO CURRENT STEP 6.0 QC5 Comment: INSPECT WORK TO CURRENT STEP HAND FINISHING1 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 8.0 QC3 07-01-17 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION Anchor nuts 9.0 4.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: Anchor nuts 10.0 Comment: Qty.: 8.0000 Each(s) 2.0000 Each(s)/Unit Total: Rivet BATCH: 1021 SMALL & MEDIUM FAB RESOURCE 1 11.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 Install Nut Plates As per Dwg D3594 INSPECT WORK TO CURRENT STEP QC5 12.0 Comment: INSPECT WORK TO CURRENT STEP PACKAGING RESOURCE #1 13.0 PACKAGING 1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location:_

Dart Aerospace Ltd

W/O:		WORK ORDER (CHANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #: Fault Category:	NCR: Yes	No DQ	A:	Date: _	

					QA: N/0	C Closed:	Date:	
NCR:			WORK ORD	ER NON-CONFORMAN	CE (NCR)			
		Description of NC		Corrective Action Section	В	Varification	A	A
DATE	STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector	

NOTE: Date & initial all entries

Datę:

Thursday, 7/12/2007 10:39:30 AM

'User:

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: DOOR DOUBLER

Job Number: 33523

Part Number: D3594043

Job Number:



Seq. #:

Machine Or Operation:

Description:

14.0

QC21



FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



a storit

Dart Aerospace Ltd

W/O:			WORK ORDER (CHANGES				······
DATE	STEP	PRO	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No) .	PAR #:	Fault Category:	NCR: Yes	No DO	Δ.	Date:	

Part No:	 PAR #:	Fault Category:	NCR: Yes	No	DQA:	Date: _	
			QA: N	I/C C	losed:	Date:	


NCR: WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B			Ammanual	Ammunual	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector	
						!		-	

NOTE: Date & initial all entries



	1	l		
DESIGN	DRAW!	BY 3	DART AEROSPA HAWKESBURY, ONTARI	
CHECK	ED APPRO	VED #	D3594	REV. A SHEET 1 OF 3
07.04.13			TITLE DOUBLER	SCALE 1:1
REV	DATE		DESCRIPTIO	N
Α	0	7.04.13	NEW ISSUE	






D3594-041 DOOR DOUBLER ASSEMBLY ASSEMBLY SCALE 1:2

ANCHOR NUT

MS21069-5

QTY -041 P/N		DESCRIPTION			
Х	D3594-041	DOOR DOUBLER ASSEMBLY			
1	D3594-1	DOOR DOUBLER			
1	MS21069-5	ANCHOR NUT			
2	MS20426AD4-4	RIVET			



D3594-1 DOOR DOUBLER 1\(\hat{\lambda}\)

SHOP COPY RETURN TO **ENGINEERING** UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE WORK ORDER

(REF. DART SPEC. M6061T6S.080)
2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

PER AMS-QQ-A-250/11 OR AMS 4025 OR AMS 4027

1) MATERIAL: 6061-T6 (OR 6061-T62) ALUMINUM SHEET, 0.080 THICK,


4) IDENTIFY WITH DART P/N "D3594-041" USING FINE POINT PERMANENT INK MARKER


5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX

COPYRIGHT © 2007 BY DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.







D3594-043 FLOOR DOUBLER ASSEMBLY (D3594-044 OPPOSITE)

QTY -043	QTY -044	P/N	DESCRIPTION
X		D3594-043	FLOOR DOUBLER ASS'Y, LH
	Х	D3594-044	FLOOR DOUBLER ASS'Y, RH
1		D3594-3	FLOOR DOUBLER, LH
	1	D3594-4	FLOOR DOUBLER, RH
1	1 1 MS21069-5		ANCHOR NUT
2	2	MS20426AD4-4	RIVET

SHOP COPY RETURN TO ENGINEERING UNCONTROLLED COPY

SUBJECT TO AMENDMENT WITHOUT NOTICE

NOTES:

1) MATERIAL: 6061-T6 (OR 6061-T62) ALUMINUM SHEET, 0.080 THICK, PER AMS-QQ-A-250/11 OR AMS 4025 OR AMS 4027

(REF. DART SPEC. M6061T6S.080)
2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED


4) IDENTIFY WITH DART P/N "D3594-043/-044" USING FINE POINT PERMANENT INK MARKER


5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED

6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX



	ľ		l				
DESIGN		DRAWI	BY	DART AEROSPACE LTD			
1 _4	3		3	HAWKESBURY, ONTARIO, CANADA			
CHECK	ED _{III} .	APPRO	VED,/	DRAWING NO.	REV. A		
			A	D3594	SHEET 3 OF 3		
DATE				TITLE	SCALE		
	07.04.13		DOUBLER	1:3			





D3594-3 FLOOR DOUBLER (D3594-4 OPPOSITE)

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE

WORK ORDER 3

DART, AEROSPACE LTD	Work Order:	33277	
Description: Place Doubles, LH	Part Number:	D 3594-	=
Inspection Dwg: Rev: A		Page 1 of 1	

FIRST ARTICLE INSPECTION CHECKLIST

Prototype

First Article

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
12.24	4030	12.24	*			
7.85	4 030	7.85	*			
7.313	4/010	1:313	*			
2.688	4010	2.627	4			
Ø .333	+ 006001	,324	*			
Ø .129	t.006 - 001	129	74			
,359	4/- 1010	.359				
،٦١8	+/do	.718	*			
. 81	4- 1030	.81	¥			
2.35	+/630	1236	7\$	-		
	ú					
				•		•
The second of the second secon						

Measured by:	ι D	Audited by:	Prototype Approval:	
	67-67-13	Date: 07/07/16	Date:	
	01-01-13	// 183		

Rev	Date	Change	0	Revised by	Approved
A		New Issue	10 - 1043	KJ/RF	



Jason Murdoch

From: David Shepherd [dshepherd@dartaero.com]

Sent: Wednesday, July 18, 2007 3:45 PM

To: 'Jason Murdoch'

Cc: 'L Lacelle'
Subject: RE: NCR's

As these parts are for the D412-698-023 Door Opener Kit and the rivet holes are used to install a nutplate, the rework you have outlined below is acceptable to me.

David

From: Jason Murdoch [mailto:jmurdoch@dartaero.com]

Sent: Wednesday, July 18, 2007 11:35 AM

To: 'David Shepherd' Subject: NCR's

Good afternoon. I had 4x D3594-043 doublers B33523, and 4x D3594-044 doublers B33524, that needed to be re-worked. For the -044, 2 parts were incorrectly counter sunk, resulting in the hole being slightly over sized. For the -043, 1 part was counter sunk too deep, which would have resulted in a bad assembly, meaning in correct riveting (a tiny gap between the material, and the rivet head). I had the parts re-worked by filling the holes necessary with weld, seeing as how the material was 6061-T6, and ground flush to the surface, then transfer drilled too the drawing. The hole sizes were only 0.129". Is this acceptable to you?

jmurdoch@dartaero.com O.C. COORDINATOR

No virus found in this incoming message.

Checked by AVG Free Edition.

Version: 7.5.476 / Virus Database: 269.10.8/906 - Release Date: 7/17/2007 6:30 PM

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.476 / Virus Database: 269.10.8/906 - Release Date: 7/17/2007 6:30 PM